



CT21076HMX

| Pos.No. | Part No. | Description | Qty | Remark |
|----------------|-----------------|------------------------------|------------|---------------|
| 1 | 34837500101 | Countersunk head screw\M6x27 | 1 | |
| 2 | 34120100101 | Chuck | 1 | |
| 3 | 00199300201 | Gear box assembly | 1 | |
| 3-1 | 34799600101 | Tapping screw\ST2.9x12F | 3 | |
| 3-2 | 33513200101 | Washer | 1 | |
| 3-3 | 33871700101 | Bearing cover | 1 | |
| 3-4 | 35240900101 | Spring | 1 | |
| 3-5 | 33513100101 | Bush | 1 | |
| 3-6 | 30184400101 | Torque sleeve | 1 | |
| 3-7 | 33278600101 | Spindle | 1 | |
| 3-8 | 35408100101 | Ball bearing\6801.2Z | 1 | |
| 3-9 | 32049500101 | O ring | 1 | |
| 3-10 | 33871800101 | Torque adjusting body | 1 | |
| 3-11 | 30184300101 | Spring holder | 1 | |
| 3-12 | 35241000101 | Spring | 12 | |
| 3-13 | 33513300101 | Washer | 1 | |
| 3-14 | 34803900101 | Pin | 6 | |
| 3-15 | 34803700101 | Tapping screw\ST3.5x16C | 4 | |
| 3-16 | 33871500101 | Front decrator cover | 1 | |
| 3-17 | 35402300201 | Ball bearing\689.2Z | 1 | |
| 3-18 | 30184500101 | Gear case cover | 1 | |
| 3-19 | 34807300101 | Washer | 1 | |
| 3-20 | 32613200101 | Spindle lock ring | 1 | |
| 3-21 | 34805900101 | Pin | 5 | |
| 3-22 | 32613300101 | Locking plate | 1 | |
| 3-23 | 32613100101 | Third sun gear | 1 | |
| 3-24 | 33020100101 | Third planet gear | 10 | |
| 3-25 | 33020300101 | Third ring gear | 1 | |
| 3-26 | 34803200101 | Washer | 1 | |
| 3-27 | 33020200101 | Second sun gear | 1 | |
| 3-28 | 30183500101 | Gear case cover | 1 | |
| 3-29 | 35238500101 | Speed change wire | 1 | |
| 3-30 | 30280500101 | Second ring gear | 1 | |
| 3-31 | 33020000101 | First sun gear | 1 | |
| 3-32 | 33019800101 | First planet gear | 5 | |
| 3-33 | 33019900101 | First ring gear | 1 | |
| 3-34 | 34813300101 | Washer | 1 | |
| 3-35 | 30183600101 | Motor cover | 1 | |
| 4 | 00100100101 | Motor gear assembly | 1 | |
| 4-1 | 33020600101 | Pinion | 1 | |
| 4-2 | 20541800101 | Motor assembly | 1 | |
| 5 | 30355800101 | Speed trigger | 1 | |
| 6 | 35238300101 | Spring | 1 | |
| 7 | 30231000201 | F/R lever | 1 | |
| 8 | 37704500101 | Magnet ring | 2 | |
| 9 | 00199300271 | Housing support | 1 | |
| 10 | 30184000101 | LED cover | 1 | |
| 11 | 34721500201 | Hex nut\M3 | 2 | |

| | | | | |
|------|-------------|------------------------------|----|---------|
| 12 | 00199300261 | Switch assembly | 1 | |
| 12-1 | 36415600901 | Switch | 1 | |
| 12-2 | 20903200101 | PCB assembly | 1 | |
| 12-3 | 30363600101 | Housing contact plate holder | 1 | |
| 13 | 00199300271 | Housing cover | 1 | |
| 14 | 34732300201 | Tapping screw\ST3x12 | 12 | |
| 15 | 02703300201 | Battery pack assembly 2Ah | 1 | |
| 15 | 02703400301 | Battery pack assembly 4Ah | 1 | |
| 15 | 02703400401 | Battery pack assembly 4Ah | 1 | For CIS |
| 16 | 02752100201 | Charger assembly CAC202001X | 1 | |
| 16 | 02752200301 | Charger assembly CAC204001X | 1 | |
| 16 | 02752200401 | Charger assembly CAC204001X | 1 | For CIS |
| 17 | 33639000102 | Belt buckle | 1 | |
| 18 | 34740300201 | Screw\ST3x12 | 1 | |
| 19 | 20048700101 | Handle assembly | 1 | |
| 19-1 | 33514100101 | Clamp ring | 1 | |
| 19-2 | 30307100101 | Support | 1 | |
| 19-3 | 30300400101 | Knob | 1 | |
| 19-4 | 34811000101 | T bolt\M8x50 | 1 | |
| 19-5 | 33419700101 | Staff gauge pole | 1 | |
| 19-6 | 30307000301 | Handle | 1 | |